

 <b>CI Plus LLP</b>	<b>Change Number</b>	<b>013</b>
<b>Title</b>	CI Plus Specification v1.3.1	
<b>Summary</b>	Errata update to the existing CI Plus Specification v1.3.	

<b>1.</b>	<b>Date of Notice</b>	3 <sup>rd</sup> October 2011	
	<b>Publication Date</b>	14 <sup>th</sup> October 2011	
	<b>Effective Date</b>	1 <sup>st</sup> August 2012	
	<b>Directly Affected Documents</b>		
	CI Plus Specification v1.3		
	<b>Detailed Change Description</b>		
	<b>General</b>		
	The CI Plus Specification v1.3 has been updated with errata items arising from the original publication. A summary of the changes in the specification is defined as follows:		
	<ul style="list-style-type: none"> <li>• Registered Service Mode clarification [5.4.2]</li> <li>• Clarification of Operator Profile including: <ul style="list-style-type: none"> <li>○ profile type 0 usage [14.7.2]</li> <li>○ Host initiated cancel [14.7.5.9]</li> <li>○ operator_status [14.7.5.3]</li> <li>○ operator_info [14.7.5.7]</li> </ul> </li> <li>• Clarifications to PIN [5.11,11.3.2] and license handling [5.10]</li> <li>• Security improvements to Host Control v2 [14.6.2.1]</li> <li>• Clarification of the SAS Resource [11.4.2]</li> <li>• Clarification to CICAM upgrade progress reporting [14.3.5.4]</li> <li>• Miscellaneous typographic corrections.</li> </ul>		
<b>2.</b>	<b>CI Plus LLP Change Request Approval/Confirmation:</b>		
	<b>Comments:</b>	<p>This specification was reviewed and approved for publication by the CI Plus Technical Group on 22<sup>nd</sup> September 2011.</p> <p>CI Plus Specification updated to version 1.3.1</p> <p>The CI Plus Specification v1.3 (and errata) has a 18 month sunrise and becomes a mandatory requirement on 1<sup>st</sup> August 2012, as defined by the CI Plus Device Interim License Agreement, section 6.3.1.</p>	
	<b>Date</b>	3 <sup>rd</sup> October 2011	<b>Signature CI Plus LLP</b> CI Plus Technical